

Hussong Manufacturing Co., Inc. announces a Recall of Kozy Heat, Ambience, and Big Woods Hearth Products Using an American Flame Intermittent Pilot Ignition (IPI) Main Control Module.



Hazard: Under certain environmental conditions the American Flame Main Control Module as used in the affected fireplaces and fireplace inserts can prematurely release burner gas, which may result in a delayed ignition.

Recalled Product: Kozy Heat, Ambiance, and Big Woods Hearth Products fireplaces manufactured from October 2009 to April 2013 using an American Flame IPI Main Control Module manufactured for Kozy Heat.

Identifying Fireplace Make & Model: You can identify your make and model of your fireplace either by the cover of your owners manual or the test lable located next to the gas valve.

Affected Model Numbers: CSK-31-IPI, CSK-335-IPI, 911-IPI, 911XL-IPI, JOR-30, JOR-34, MPS-30, MPS-34, RFD-30, RFD-34, NCL-195, DSL-36-IPI, DEL-36-IPI, PRC-36-IPI, 56701-IPI, 55345-IPI, TMT-3875-IPI, SLA-42, INT-100, INT-200, CML-58-S, CML58-S.

Remedy: Consumers should stop using their fireplace immediately and contact their dealer where the fireplace was purchased for more details. If your dealer is no longer in business or you are unsure who your dealer is, please contact the number below for assistance.

For More Information:

800-253-4904

Monday through Friday 7:30am to 5:00pm CST www.kozyheat.com/afrecall

This safety notification is being conducted in cooperation with the U.S. Consumer Product Safety Commission.

Posted: Until 07/03/14